



NOTES

- 1. Pre Slit Support Column: (1) required
- 2. Center flanges on pipe and align rotation with respect to each other
- 3. After fabrication, sandblast, prime, and paint white

3	1	PS support flange 2 - 3 X 3 X 1/2 Mild steel
2	1	PS support flange 1 - 3 X 3 X 3/8 Mild steel
1	1	PS support column - 1 1/2" SCH 40 pipe (1.9" OD)
ITEM	QTY	DESCRIPTION
Bill of Material		
THE OBSERVATORIES OF THE CARNEGIE INSTITUTION OF WASHINGTON 813 Santa Barbara Street Pasadena, CA 91101		
MATERIAL	Mild Steel	UNLESS OTHERWISE SPECIFIED FRACTIONAL DECIMAL ANGULAR +/- 1/32 .XX +/- 0.01 +/- 0.1 DEG .XXX +/- 0.002 GOAL .XXX +/- 0.005 REQD BREAK SHARP EDGES MACHINED SURFACES 125 ✓ ALL DIMENSIONS IN INCHES
EST WEIGHT	5.8 lb	
SCALE	1:3	P lanet F nder S pectrograph
DWN	CRANE	6/21/2007
APVD	BY	DATE
SHEET	DRAWING NUMBER	SHT 1 OF 1
B	PFS04070	REV 1